



M-2

Max. Torque: 1300 Ft. Lbs.

Description	A	B	C	D	E	F	G	H
M-2 with 1-1/16" hex	.375"	.99"	.611"	3.28"	.99"	.75"	1.25"	6.96"
M-2 with 1-1/4" hex	.375"	1.10"	.611"	3.28"	1.10"	.75"	1.25"	6.96"
M-2 with 1-7/16" hex	.375"	1.20"	.611"	3.28"	1.20"	.75"	1.25"	6.96"
M-2 with 1-5/8" hex	.375"	1.31"	.611"	3.28"	1.31"	.75"	1.25"	6.96"
M-2 with 1-13/16" hex	.375"	1.42"	.611"	3.28"	1.42"	.75"	1.25"	6.96"
M-2 with 2" hex	.375"	1.53"	.611"	3.28"	1.53"	.75"	1.25"	6.96"
M-2 with 2-3/16" hex	.375"	1.64"	.611"	3.28"	1.64"	.75"	1.25"	6.96"
M-2 with 2-3/8" hex	.375"	1.75"	.611"	3.28"	1.75"	.75"	1.25"	6.96"

M-8

Max. Torque: 6,000 Ft. Lbs.

Description	A	B	C	D	E	F	G	H
M-8 with 2-3/16" hex	.625"	1.89"	1.02"	5.47"	1.89"	1.25"	2.09"	11.60"
M-8 with 2-3/8" hex	.625"	2.00"	1.02"	5.47"	2.00"	1.25"	2.09"	11.60"
M-8 with 2-9/16" hex	.625"	2.10"	1.02"	5.47"	2.10"	1.25"	2.09"	11.60"
M-8 with 2-3/4" hex	.625"	2.21"	1.02"	5.47"	2.21"	1.25"	2.09"	11.60"
M-8 with 2-15/16" hex	.625"	2.32"	1.02"	5.47"	2.32"	1.25"	2.09"	11.60"
M-8 with 3-1/8" hex	.625"	2.43"	1.02"	5.47"	2.43"	1.25"	2.09"	11.60"
M-8 with 3-7/8" hex	.625"	2.86"	1.02"	5.47"	2.86"	1.25"	2.09"	11.60"

M-4

Max. Torque: 3080 Ft. Lbs.

Description	A	B	C	D	E	F	G	H
M-4 with 1-13/16" hex	.50"	1.55"	.815"	4.38"	1.55"	1.00"	1.67"	9.28"
M-4 with 2" hex	.50"	1.65"	.815"	4.38"	1.65"	1.00"	1.67"	9.28"
M-4 with 2-13/16" hex	.50"	1.76"	.815"	4.38"	1.76"	1.00"	1.67"	9.28"
M-4 with 2-3/8" hex	.50"	1.87"	.815"	4.38"	1.87"	1.00"	1.67"	9.28"
M-4 with 2-9/16" hex	.50"	1.98"	.815"	4.38"	1.98"	1.00"	1.67"	9.28"
M-4 with 2-3/4" hex	.50"	2.09"	.815"	4.38"	2.09"	1.00"	1.67"	9.28"
M-4 with 2-15/16" hex	.50"	2.19"	.815"	4.38"	2.19"	1.00"	1.67"	9.28"
M-4 with 3-1/8" hex	.50"	2.30"	.815"	4.38"	2.30"	1.00"	1.67"	9.28"

For more information or for specific repair needs, Alltite's Customer Support Center has solutions for your immediate problems.